

Miami-Dade County Public Schools Department of Asbestos Management Periodic Surveillance Report

Building Name and #: **FLOYD GLORIA ELEM.**

2021

Site Administrator: Felicia K. Joseph

12650 SW 109 AV.

Inspector: ROBINSON GAVIRIA

MIAMI FL 33176

Certificate #: R070319-8297

Previous: Semiannual Survey Date 9/20/2010

Current: Semiannual Survey Date 5/17/2011

Room	Suspect Material	Type Material	Access-ibility	Air Erosion	ASHERA Previous	ASHERA Current	Change in Condition	Response Action	Comments
117 BLDG 01 AHU	A/C duct mastic(Blk) Black Tar	Misc	N/A	N/A	0	0	None	Removed	
149 BLDG 01 FOOD SERV	A/C duct mastic(Blk) Black Tar	Misc	Low	Low	5	5	None	O & M	
155 BLDG 01 MAT STO	A/C duct mastic(Blk) Black Tar	Misc	Low	Low	5	5	None	O & M	
157A BLDG 01 AHU	A/C duct mastic(Blk) Black Tar	Misc	N/A	N/A	0	0	None	Removed	
158 BLDG 01 KTCH	A/C duct mastic(Blk) Black Tar	Misc	Low	Low	5	5	None	O & M	
158A BLDG 01 FOOD SERV	A/C duct mastic(Blk) Black Tar	Misc	Low	Low	5	5	None	O & M	
158C BLDG 01 EQUIP RM	A/C duct mastic(Blk) Black Tar	Misc	Low	Low	5	5	None	O & M	
160 BLDG 01 DISH WASH	A/C duct mastic(Blk) Black Tar	Misc	Low	Low	5	5	None	O & M	
160A BLDG 01 MECH	A/C duct mastic(Blk) Black Tar	Misc	Low	Low	5	5	None	O & M	
228 BLDG 01 MECH RM	A/C duct mastic(Blk) Black Tar	Misc	N/A	N/A	0	0	None	Removed	
COOLING TOWER BLDG 02	Eliminators White Mat	Misc	N/A	N/A	0	0	None	Removed	
RM 233 BLDG 01	A/C duct mastic(Blk) Black Tar	Misc	N/A	N/A	0	0	None	Removed	
ROOF BLDG 02	Transite Cementitious	Misc	N/A	N/A	0	0	None	Removed	

Inspector's Signature _____

Classification of ACBM

- | | | |
|---|---|---|
| 1. Damaged or significantly damaged thermal system insulation ACM | 3. Significantly damaged friable surfacing ACM | 5. ACBM with potential for damage |
| 2. Damaged friable surfacing ACM | 4. Damaged or significantly damaged friable miscellaneous ACM | 6. ACBM with potential for significant damage |
| | | 7. Any remaining friable ACBM or suspected ACBM |